
## CERTIFICATE OF MAILING



Paulo D. Kiser

Practitioner's Docket No.: 2001-0607.03



cofe

## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

Applicant:

Anderson, et al.

Group No.:

Application No.:

10/765,513

Examiner:

Alfred E. Dudding

Filed:

January 27, 2004

Issued:

December 14, 2004

Patent No.:

6,830,307

For:

Integrated Circuit and Drive Scheme For An Inkjet Printhead

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 C.F.R.§ 1.322 AND 1.323

Dear Sir:

The Patentees respectfully request that the attached Certificate of Correction be issued under 37 C.F.R. § 1.322 and 1.323 for the above-identified patent. The following mistakes are believed to be printing errors.

The first mistake is found in claim 1, column 10, line 17, replace "inkiet" with - - inkjet - -. The next mistake is in claim 4, column 11, line 30, insert - - lines - - after "control". The third error is in claim 5, column 11, line 50, insert - - lines - - after "control". The final error is in claim 8, column 12, line 27, replace "chat" with - - that - -.

Correction of the above-identified errors is believed necessary to avoid any possible ambiguity with respect to the claims. A Certificate of Correction Form PTO/SB/44 (in duplicate) is included for printing by the Patent and Trademark Office. Although no fee is believed due, the Commissioner is hereby authorized to charge any fee due for such Certificate of Correction to Deposit Account No. 12-1213. A duplicate copy of this paper is enclosed herewith for this purpose.

Respectfully submitted,

Scott N. Barker, Reg. No. 42,292

Lexmark International, Inc.

Intellectual Property Law Department

740 W. New Circle Rd.

Lexington, KY 40550 U.S.A.

(859) 232-3668

Customer No. 21972

ALP L TOPE